ICECAPS-ACE Weekly Report

December 17 – December 23, 2018 Gus Allen



Happy Winter Solstice from the Summit winter crew!

General:

We were able to swap out about 50 empty helium tanks for full ones in the SMG, which should make balloon launches for the remainder of the winter season slightly more efficient. The ACE laptop appears to have an issue which is undiagnosed as of this writing.

Date	Time (Z)	Wind	Weather	Visibility	Sky	Temp	Notes
12-17	13Z	24kt from 100	FZFG	0400	BKN000 BKN060	-30	
			BLSN				
12-18	12	14kt from 150	FZFG	0600	BKN000	-34	
			BLSN				
12-19	12	20kt from 150	BLSN	0400	BKN000	-22	
12-20	12	14kt from 185	BLSN	0400	BKN000 BKN080	-27	
12-21	12	14kt from 230	BLSN	400	VV000	-25	
12-22	12	9kt from 230	-SN BLSN	800	SCT000 BKN100	-34	
			IC				
12-23	12	16kt from 200	SN BLSN	0400	VV006	-26	

Significant Weather Observations:

ICECAPS-ACE Data Management:

- 12-17: Data transfer complete at 1410Z
- 12-18: Data transfer complete at 1451Z
- 12-19: Data transfer complete at 1520Z
- 12-20: Data transfer complete at 1419Z
- 12-21: Data transfer complete at 1650Z
- 12-22: Data transfer complete at 1416Z
- 12-23: Data transfer complete at 1443Z

MWR:

• Operating normally.

SODAR:

- 12-23 1505–1518Z: Amp powered off to allow snow removal from dishes.
- Operating normally.

POSS:

• Operating normally.

MMCR:

• Operating normally.

CAPABL:

• Instrument currently operating normally using laser 2

MPL:

- 12-20 1406Z 1436Z: Afterpulse Calibration performed.
 - o 30m, 30s: 1416Z-1424Z

•	CoPol Background Avg	.000341	
•	CoPol Std. Dev.	.000203	

- File: 201812201416.mpl
- o 15m, 30s: 1426Z-1434Z

CoPol Background Avg .000314

- CoPol Std. Dev. .000286
- File: 201812201426.mpl
- Operating normally.

VCEIL:

• Operating normally.

IceCAM:

• Operating normally.

PAERI:

• Operating normally.

TSI:

• Offline for winter season.

IcePIC:

• No images captured this week.

Radiosonde:

• Twice daily launches.

MASC:

• Instrument offsite for repair, will not return until summer 2019.

OPC:

- 12-20: OPC removed from the roof because the intake appeared blocked by rime.
- 12-21: ACE laptop found unresponsive. ACE mount on ICECAPS system also appears to not be present. I contacted Neely and Heather.
- 12-22: At Neely's direction, I performed a hard reboot on the ACE laptop.
- 12-22 1915Z: OPC remounted and data collection started.
- 12-23: ACE laptop unresponsive.

CLASP:

• Instrument off site.

CPC:

• Instrument off site.