# **ICECAPS** Weekly Report

October 10, 2016 – October 16, 2016 Elissa Barris, Travis Guy



Cool backdrop for a balloon launch, and a welcome change from blowing snow. -Travis, 10/17

### General:

• Brief daily internet interruptions at ~1300z due to solar interference.

# **Significant Weather Observations:**

- 10/10: Bkn altostratus, DRSN, -27C, 13kn, Visibility 800m. Halo 1333z
- 10/11: Sct cirrus giving way to Ovc stratus, -22C, 7kn, 1600m. Parhelia 1105z. Fogbow 1308z.
- 10/12: Ovc stratus, -18C, 25kn, BLSN, Visibility 400m.
- 10/13: Ovc stratus, -18C, 22kn, BLSN, Visibility 300m. Slight clearing in the afternoon. Parhelia 1606z.
- 10/14: Bkn, stratus and altocumulus, -20C, 27kn, BLSN, Visibility 200m, dropping down to less than 100m in the afternoon.
- 10/15: Bkn stratus, -15C, 24kn, BLSN, Visibility 200m. Paraselene 0234z and 2244z.
- 10/16: Few stratus, Sct Altostratus, Bkn cirrus, -22C, 15kn, DRSN, FZFG, Visibility 1600m dropping to 600m. Halo ~1200z and lasting throughout most of the afternoon.

## **Dataman Account:**

- 10/10: Data transfer complete at 1114z.
- 10/11: Data transfer complete at 1215z.
- 10/12: Data transfer complete at 1103z.
- 10/13: Data transfer complete at 1542z.
- 10/14: Data transfer complete at 1536z.
- 10/15: Data transfer complete at ????z. Had to initiate manual transfer at ~1400z to restart upload after internet interruption. Transfer was close to complete at this time.
- 10/16: Data transfer complete at 1115z.

#### MWR:

• Operating normally.

## **SODAR:**

• Operating normally.

## **POSS:**

• Operating normally.

## **MMCR:**

- Operating normally.
- TWTA Cathode Voltage out of range throughout week.
- The following errors were seen in the elog throughout the week:
  - Level 2 NetCDF Spec Could not read calibration table NetCDF file.
  - Level 2 NetCDF Spec Data may be incorrect.
  - Level 2 NetCDF Mom Could not read calibration table NetCDF file.
  - Level 2 NetCDF Mom Data may be incorrect.
- Pitch 0.11, roll -0.11 as of 10/15.

## **CAPABL:**

• Operating normally.

## MPL:

• Operating normally.

#### VCEIL:

• Operating normally.

## **Hotplate:**

• Off site for repairs since 6/9/2016.

# **IceCAM:**

• Operating normally.

#### PAERI:

Operating normally.

# TSI:

Operating normally.

## IcePIC:

• 8/XX Slides placed for collection XXXXXz. Images photographed include XXXXXXXX.

## Radiosonde:

- Twice daily soundings.
- 11/14: Night sonde lost satellite reception either right before or immediately after launch. We had trouble getting satellites while doing the conditioning as well. A 2<sup>nd</sup> launch was successful.

#### MASC:

• Offsite for repairs since 5/3/2016.